Date: October, 11, 2005

## AKAI professional = SERVICE BULLETIN =

DPS24 V1.61 has been released with the following bug fixes and improvements from V1.60.

## [Bug fix/improvement]

- \* Improved IDE driver fixes problems with support of certain CD-ROM drives. (EPO CDRW CRW-5232)
- \* Fixes problem with CD player time display.
- \* Improved handling of projects containing large amounts of data fixes problem of crashing when reloading projects after disk copy operation.

(Note: we recommend the DPS24 being power Off/On after copying a very large project (over 60GB) between internal ATA Hard disks).

## [Note]

O.S. V1.61 for DPS24 will be uploaded on AKAI professional web-site.

Addendum operator's manual for V1.61 will not be issued.